BRUNSING ASSOCIATES, INC.

P.O. BOX 588

Windsor, CA. 95492 Telephone: (707) 838-3027 Fax: (707) 838-4420

SURFACE ELEVATION:

COORDINATES:

BORING NO.:

B-2

SHEET

1 OF 1

PROJECT:

COTATI STATION

LOCATION:

Cotati, California

PROJECT NO.: 771

SMS LOGGED BY:

SURFAC	CE ELEVA	TION:		DATE	JIVI.	LOGGED B1: SINO			
DEPTH FEET	SAM LAB SAMPLE	PLE INF		Recovery	PID (ppm)	DESCRIPTION	STRATA	WELL CONSTRUCTION DETAIL	N
10-			6 9 18 9 9 10		0.0	DARK BROWN SILTY CLAY (CL) dry to moist, medium stiff to stiff, ~5% fine to very fine-grained sand, ~10% silt, ~85% clay BROWN CLAY (CL) moist, medium stiff, trace medium-grained sand, ~15% silt, ~85% clay BROWN CLAYEY SILTY SANDY GRAVEL (GC) dry to moist, medium dense, ~40% gravel, ~30% very coarse to very fine-grained sand, ~15% silt, ~15% clay, subangular gravel up to 32mm BROWN SILTY CLAY (CL) moist to wet, medium stiff, trace subangular gravel up to 14mm, trace medium to fine-grained sand,~15% silt, ~85% clay		₽	5- 10- 20-
DRILI DRILI	ING CON ING MET ING EQU ING STA	IPMENT:	6-inch	hollow s			o 21.5	5' BGS	
DRILLI DRILLI		BRUNS	ING ASS	OCIATES	, INC.	Date: 2/10/05 COTAT S348 Sa Cotati,	I STAT antero	ION Way	PLATE 5

DATUM: